



R-825

LARGE DIAMETER BORED PILE

Working Condition



* May be obtained by removing the lower mast element